





KFlop+KStep wiring diagram with DC motor controller and relay



KFLOP - Connector Pinouts




JP33



JP33 IO
Relay Drv Out
Opto IN
Analog Out



Unsure of the connection to "switch" the relay on and off



Spindle speed control