

Changes KFLOP and KMotion Released Versions 4.31 -> 4.32 04/12/2014

KMotionCNC

Fix Spindle Buttons not working after Simulate